

MLA Trouble Shooting

| Not Aspirating Properly | | |
|--|--|--|
| Possible Cause | Suggested Fix | |
| Foreign material in body/ nozzle assembly restricting plunger movement or air flow | Dissemble pipette according to Seal Kit instructions and clean interior with 70% isopropyl alcohol. Replace seals, lubricate and calibrate. | |
| | Send into VistaLab for Repair service (replacement parts included) | |
| Body/ Nozzle Assembly loose | Ensure that body of pipette is tightly screwed together. See Seal Kit instructions for instructions on proper disassembly/assembly. | |
| Seals worn, eroded | Replace seals and lubricate, followed by Calibration | |
| Nozzle insert is plugged | Remove nozzle insert, clean inner nozzle assembly and replace. | |

| Plunger "sticky" or rough to operate | |
|--|--|
| Possible Cause | Suggested Fix |
| Foreign material in body/ nozzle assembly restricting plunger movement or air flow | Dissemble the pipette according to Seal Kit instructions and clean interior with 70% isopropyl alcohol. Replace seals, lubricate and calibrate. |
| | Send into VistaLab for Repair service for replacement of corroded parts. |
| Seals worn or eroded | Replace seals and lubricate, followed by Calibration |
| Plunger spring dislodged/ kinked | Send into VistaLab for Repair service (replacement parts included) |
| Plunger has become etched from chemicals fumes | Send into VistaLab for Repair service (replacement parts included) |

| D-Tipper mechanism "sticky" or rough to operate | | |
|---|--|--|
| Possible Cause | Suggested Fix | |
| Foreign material between body and sleeve | Dissemble pipette, remove sleeve and wipe down body exterior and sleeve interior | |
| Nozzle Assembly bent | Send into VistaLab for Repair service (replacement parts included) | |